

---

A PART OF THE SE $\frac{1}{4}$  IN SECTION 3, T14N, R1W, IN THE TOWN OF FOREST, VERNON COUNTY, WISCONSIN.

OAK LANE  
6' 6'  
N 89-12-33 E  
1303.37'  
E 1/4 COR.  
3-14-1W  
SURVEYOR'S CERTIFICATE

SURVEYOR'S CERTIFICATE


E 1/4 COR.  
3-14-1W

I, Patrick A. Carroll, Registered Land Surveyor S-11199, for Carroll Surveying of Mauston, Wisconsin, hereby certify:

That in compliance with the provisions of Chapter A-E 7 of the Administrative Code of the State of Wisconsin, and under the direction of BRAD VALINTINE, owner of said land, Carroll Surveying did survey, field stake at various intervals and map the north line of the SE $\frac{1}{4}$  of the SE $\frac{1}{4}$  in Section 3. T14N, R1W, in the Town of Forest, Vernon County, Wisconsin.

That such map correctly represents the exterior boundaries and the subdivision of the land surveyed and mapped to the best of my knowledge and belief.

REGISTERED LAND SURVEYOR S-1199  
PATRICK A. CARROLL APRIL 11, 1998  
CARROLL SURVEYING, MAUSTON, WIS.



and mapped to the best of my knowledge and belief.

*Patrick A. Carroll*

REGISTERED LAND SURVEYOR S-1199  
PATRICK A. CARROLL APRIL 11, 1998  
CARROLL SURVEYING, MAUSTON, WIS.

1322.33'

630.02' NORTH-SOUTH

31.63' NORTH-SOUTH

66'

PINE AVE.

N 89-26-42 E

33.00'

1294.27'

1327.27'

Fence encroachment


The north line of the SE $\frac{1}{4}$  of the SE $\frac{1}{4}$  3-14-1W

WISCONSIN  
PATRICK A. CARROLL  
S-1199  
MAUSTON  
WIS.  
LAND SURVEYOR

## LEGEND

- 1 1/4" IRON PIPE (FOUND IN PLACE)
- ✕---3/4" x 40" IRON BAR SET (WT. 1.50#/L.F.)
- ⊗---6" SPIKE NAIL (FOUND IN PLACE)
- R R SPIKE (FOUND IN PLACE)
- R R SPIKE SET
- 6" SPIKE NAIL SET
- 1" x 24" IRON PIPE SET (WT. 1.68#/L.F.)

BEARINGS ARE REFERENCED TO THE EAST LINE OF THE SE 1/4 OF SECTION 3, ASSIGNED TO BEAR S 00-14-31 E.



SCALE 1" = 200 FEET

SE COR.  
3-14-1W

1292.24'

1317.28'

N 89-40-50 E